





E Major category | **ML** Category | **T** Series | **M4** Thread specification | **L6** Length

Order guide

Please refer to the series code to select the type and parameters for ordering.

Blind hole

Code	Category	Material	Surface treatment	Thread	Strength class
EMLT	Insert nut	Brass	No	Coarse thread	A2-70





Visual standards:
first perspective

Model		L ²				Pitch P	D	L ²		Hole depth h
Code	M ¹									
EMLT	4	6	8	12		0.7	5.2	6	4	
	5	6	8	10	12	0.8	6.3	8	10	6
	6	8		10	12	1.0	8.3	12	14	10
	8	12		14	16	20	1.25	10	16	20

Through hole

Code	Category	Material	Surface treatment	Thread	Strength class
EMLU	Insert nut	Brass	No	Coarse thread	A2-70



Visual standards:
first perspective

Model		L ²								Pitch P	D
Code	M ¹										
EMLU	4	3	4	5	6	8			0.7	5.2	
	5	5				6	8	12	0.8	6.3	
	6	4	5	6	8	10	12	16	1.0	8.3	
	8	6		8	10	12	14	16	20	1.25	10